


John Deere Poly Skid Plate Covers Kits

*** Hardware included in each kit.**

*** All kits are made from 1/4" thick virgin UHMW.**

CFC Distributors, Inc. has, and always will, offer "Slippery Shoes" made of only virgin UHMW Polymer. All John Deere skid plates are made of Yellow UHMW poly. Kit includes endshoes, gearbox cover, hardware and 900 series kits also include the stabilizer cover. Each piece is predrilled and bent to match the steel plates.



200 Series Kits

| ORDER NO. | DESCRIPTION | WT. | STOCK | RETAIL |
|-----------|---|-----|--------|----------|
| KCS13JD | Poly combine skid plate kit, 13' Deere, 200 series. | 24 | 082526 | \$316.00 |
| KCS15JD | Poly combine skid plate kit, 15' Deere, 200 series. | 27 | 063721 | \$342.00 |
| KCS16JD | Poly combine skid plate kit, 16' Deere, 200 series. | 27 | 021928 | \$364.00 |
| KCS18JD | Poly combine skid plate kit, 18' Deere, 200 series. | 33 | 069235 | \$412.00 |
| KCS20JD | Poly combine skid plate kit, 20' Deere, 200 series. | 36 | 088431 | \$436.00 |
| KCS22JD | Poly combine skid plate kit, 22' Deere, 200 series. | 40 | 004045 | \$505.00 |
| KCS24JD | Poly combine skid plate kit, 24' Deere, 200 series. | 43 | 088246 | \$536.00 |

900 Series Kits

| ORDER NO. | DESCRIPTION | WT. | STOCK | RETAIL |
|-----------|---|-----|--------|----------|
| KCS13JD9 | Poly combine skid plate kit, 13' Deere, 900 series. | 27 | 088626 | \$336.00 |
| KCS15JD9 | Poly combine skid plate kit, 15' Deere, 900 series. | 30 | 002921 | \$365.00 |
| KCS18JD9 | Poly combine skid plate kit, 18' Deere, 900 series. | 36 | 008431 | \$435.00 |
| KCS20JD9 | Poly combine skid plate kit, 20' Deere, 900 series. | 39 | 000839 | \$475.00 |
| KCS22JD9 | Poly combine skid plate kit, 22' Deere, 900 series. | 43 | 002341 | \$540.00 |
| KCS24JD9 | Poly combine skid plate kit, 24' Deere, 900 series. | 46 | 000449 | \$550.00 |
| KCS25JD9 | Poly combine skid plate kit, 25' Deere, 900 series. | 49 | 025746 | \$594.00 |
| KCS30JD9 | Poly combine skid plate kit, 30' Deere, 900 series. | 48 | 008254 | \$660.00 |

600 Series Kits (600 series kit is for the standard (1.5") cut height not the raised cut (2.5") pads.)

| ORDER NO. | DESCRIPTION | WT. | STOCK | RETAIL |
|-----------|---|-----|--------|----------|
| KCS20JD6 | Poly combine skid plate kit, 20' Deere, 600 series. | | 086531 | \$446.00 |
| KCS25JD6 | Poly combine skid plate kit, 25' Deere, 600 series. | | 063931 | \$492.00 |
| KCS30JD6 | Poly combine skid plate kit, 30' Deere, 600 series. | | 042648 | \$578.00 |
| KCS35JD6 | Poly combine skid plate kit, 35' Deere, 600 series. | | 002359 | \$665.00 |



Our 600 series skid shoes have a raised rib on both edges for extra long wear. In this raised area the shoe is 1/2" thick. The rest of the skid shoe is 3/8" thick. This is a very high density UHMW poly for extra wear.



CH170502

CH205344 600 series skid shoe

CFC Distributors, Inc. Jan. 2014 Catalog

140

Phone 800-548-6633

Repair Parts for Deere 200, 900, & 600 series Poly Skid Plates

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|--|-------|---------|
| CSXJD1 | JD1 Left side, next to gear box, 46" x 16". | 36859 | \$83.76 |
| CSXJD19 | JD1 for 900 series. Left side, 16 5/8" x 52-1/2". | 69864 | \$98.51 |
| CSXJD2 | JD2 Center Plate, 17" x 16". | 13525 | \$36.16 |
| CSXJD3 | JD3 Center Plate, 19 5/8" x 16". | 02521 | \$36.00 |
| CSXJD4 | JD4 Center Plate, 8" x 16". | 07015 | \$15.29 |
| CSXJD5 | JD5 Right Side Plate, next to end shoe, 46" x 16". | 36854 | \$83.76 |
| CSXJD59 | JD5 for 900 series. Right side plate, 16 5/8" x 50".. | 69861 | \$98.52 |
| CSXJD6 | JD6 Right Side End Shoe Cover, 25-1/4" x 3-1/2". | 0198 | \$13.00 |
| CSXJD69 | JD6 for 900 series. Right side, in front of JD59, 4" x 11". | 0197 | \$13.00 |
| CSXJD7 | JD7 Gear box cover, specify 200 or 900 series. | 08917 | \$28.29 |
| CSXJD79 | JD7 for 900 series. Left side, in front of JD19, 6-3/4" x 12 3/8". | 08912 | \$28.29 |
| CSXJD23 | JD23 Stabilizer cover, behind gear box - 24" x 17". | 30335 | \$47.18 |
| CH208626 | 600 series, 8.25" x 11.5". Replaces JD no. H208626 | 2399 | \$13.32 |
| CH209696 | 600 series, 3" x 14.25". Replaces JD no. H209696 | 0861 | \$9.71 |
| CH170501 | 600 series, 9.5" x 14.5". Replaces JD no. H170501 | 05315 | \$19.29 |
| CH170502 | 600 series, 12" x 33". Replaces JD no. H170502 | 34055 | \$72.04 |
| CH205344 | Main skid shoe on 600 series, 5.5" x 9.5". Replaces JD no. H205344 | 7279 | \$10.38 |
| KBHAMA | Pkg of 50 hammer rivets for use in non countersunk holes.(200/900) | 8498 | \$13.54 |
| KBHAMAS | Pkg of 50 hammer rivets for use in countersunk holes. (200/900) | 8497 | \$13.54 |
| KBHAMJD | Pkg of 50 hammer rivets for use on JD 600 series plates. | 0891 | \$14.00 |



CSXJD19



CSXJD3



CSXJD79



CSXJD69



CSXJD4



CH209696



CSXJD59



CSXJD23



CH208626


Hart Carter Gen III Poly Skid Plate Covers Kits

Produced from 1/4" thick virgin white UHMW poly, pre-formed and undrilled.
Kits include a drill bit and hammer rivets.

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|-------------------------|--------|----------|
| KCS13HC | Slippery shoe kit, 13'. | 061215 | \$152.00 |
| KCS15HC | Slippery shoe kit, 15'. | 021516 | \$189.00 |
| KCS20HC | Slippery shoe kit, 20'. | 025711 | \$219.00 |

Repair Parts for Hart Carter Gen III Floating Heads


| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|-------|---------|
| CSXHC29 | Repair part, 18" x 7". | 33115 | \$16.18 |
| CSXHC30 | Repair part, 33 3/4" x 7". | 15226 | \$32.15 |
| CSXHC31 | Repair part, 44 1/2" x 7". | 12035 | \$43.15 |
| CSXHC32 | Repair part, 18" x 15". (Gen 2) | 59221 | \$32.79 |
| CSXHC33 | Repair part, 8" x 12". (Gen 2) | 9288 | \$11.84 |
| KBHAMA | Pkg of 50 hammer rivets for use in non countersunk holes. | 8498 | \$13.54 |
| KBHAMAS | Pkg of 50 hammer rivets for use in countersunk holes. | 8497 | \$13.54 |



Agco-Gleaner 300/500/800 & Challenger Poly Skid Plate Kits

Produced from 1/4" thick virgin, white UHMW poly, pre-bent. All kits include gear box cover and right hand end shoe. Hammer rivets are included in the kit price.

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|--------|----------|
| KCS13AC | Slippery shoe kit for 13' flex head. | 084236 | \$406.00 |
| KCS15AC | Slippery shoe kit for 15' flex head. | 021535 | \$439.00 |
| KCS15AC5 | Slippery shoe kit for 15' 500 series heads. | 080836 | \$476.00 |
| KCS16AC | Slippery shoe kit for 16' flex head. | 042834 | \$478.00 |
| KCS18AC | Slippery shoe kit for 18' flex head. | 027831 | \$484.00 |
| KCS18AC5 | Slippery shoe kit for 18' 500 series heads. | 023245 | \$529.00 |
| KCS20AC | Slippery shoe kit for 20' flex head. | 023245 | \$529.00 |
| KCS20AC5 | Slippery shoe kit for 20' 500 & 800 series heads. | 029544 | \$574.00 |
| KCS22AC | Slippery shoe kit for 22' flex head. | 029547 | \$574.00 |
| KCS22AC5 | Slippery shoe kit for 22' 500 & 800 series heads. | 088056 | \$636.00 |
| KCS24AC | Slippery shoe kit for 24' flex head. | 086154 | \$646.00 |
| KCS25AC | Slippery shoe kit for 25' flex head. 500 or 800 series. | 000451 | \$675.00 |
| KCS26AC | Slippery shoe kit for 26' flex head. 300 series. | 023451 | \$679.00 |
| KCS30AC | Slippery shoe kit for 30' flex head. 500 or 800 series. | 027859 | \$734.00 |



CSXAC26

CSXAC35

CSXAC22L

Repair Parts for Agco 300/500/800 Series Heads

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|-------|---------|
| CSXAC15 | Repair part, 37 1/8" x 14". | 61648 | \$65.94 |
| CSXAC16 | Repair part, 29 1/2" x 14". | 56635 | \$52.35 |
| CSXAC17 | Repair part, 11 1/2" x 14". | 33415 | \$20.47 |
| CSXAC18 | Repair part, 36 3/4" x 14". | 24546 | \$64.88 |
| CSXAC19 | Repair part, 17 1/2" x 14". | 38125 | \$31.18 |
| CSXAC20 | Repair part, 23 5/8" x 14". | 14826 | \$40.59 |
| CSXAC21 | Repair part, 48 3/4" x 14". | 35064 | \$86.47 |
| CSXAC22L | Repair part, 35 1/2" x 14". | 91445 | \$63.13 |
| CSXAC22R | Repair part, 35 1/2" x 14". | 91441 | \$63.13 |
| CSXAC23 | Repair part, 48 1/4" x 14". | 77951 | \$85.39 |
| CSXAC24 | Repair part, 40" x 14" | 46948 | \$70.91 |
| CSXAC25 | Repair part, 38 5/8" x 14" specify Left or Right. | 77748 | \$68.24 |
| CSXAC26 | Repair part, 5 1/2" x 24 3/8". End shoe on 300 series only. | 30918 | \$27.18 |
| CSXAC27 | Repair part, 26 5/8" x 14". | 01045 | \$57.29 |
| CSXAC28 | Repair part, 9 3/4" x 8 1/2". | 7177 | \$10.24 |
| CSXAC29 | Repair part, gear box cover, 11" x 24". | 49231 | \$47.06 |
| CSXAC30 | Repair part, 50" x 14" (used on 300 series 26'). | 84055 | \$72.12 |
| CSXAC32 | Repair part, 46" x 14". | 58744 | \$68.35 |
| CSXAC33 | Repair part, 55 3/8" x 14". | 19259 | \$75.59 |
| CSXAC34 | Repair part, 45 7/8" x 14". | 48156 | \$74.06 |
| CSXAC35 | Repair part, 24 3/8" x 3 1/2". End shoe on 500 or 800 series. | 6188 | \$11.65 |
| CSXAC36L | Repair part, 38 5/8" x 14" used on 500 and 800 series only. | 54336 | \$47.78 |
| CSXAC36R | Repair part, 38 5/8" x 14" used on 500 and 800 series only. | 54335 | \$47.78 |
| KBHAMA | Pkg of 50 hammer rivets for use in non contersunk holes. | 8498 | \$13.54 |
| KBHAMAS | Pkg of 50 hammer rivets for use in contersunk holes. | 8497 | \$13.54 |

Love & Hiniker Poly Skid Plate Repair Parts

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|-------------------------------------|-------|---------|
| CSXHN10 | Repair part for Hiniker, 17" x 16". | 02235 | \$46.00 |
| CSXLV12 | Repair part for Love, 14" x 12". | 09521 | \$37.00 |
| CSXLV17 | Repair part for Love, 14" x 17". | 05135 | \$45.00 |
| CSXLV18 | Repair part for Love, 18" x 18". | 64835 | \$54.94 |

ORDERING INFORMATION: We generally can make custom skid plates for most applications. During most of the year we can custom cut your poly within 24 to 48 hours.

New Holland Flex Poly Skid Plate Covers Kits

Produced from 1/4" thick virgin white UHMW poly, 973 kits are pre-bent, pre-drilled, and countersunk to match newer pre-drilled skid plate design. 973 kits include front and rear dividers. Installs with hammer rivets.

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|------------|--|--------|----------|
| KCS15NHF | Slippery shoe kit, 15' for 972 flex head. | 027833 | \$411.25 |
| KCS20NHF | Slippery shoe kit, 20' for 972 flex head. | 025948 | \$523.75 |
| KCS16NH973 | Slippery shoe kit, 16' for 972/973, 73C flex head. | 029933 | \$423.75 |
| KCS18NH973 | Slippery shoe kit, 18' for 973, 73C flex head. | 021744 | \$498.75 |
| KCS20NH973 | Slippery shoe kit, 20' for 973, 73C flex head. | 008256 | \$561.25 |
| KCS22NH973 | Slippery shoe kit, 22' for 973, 73C flex head. | 021558 | \$586.25 |
| KCS24973 | Slippery shoe kit, 24' for 973, 73C flex head. | 065858 | \$622.50 |
| KCS25NH973 | Slippery shoe kit, 25' for 973, 73C flex head. | 027855 | \$623.75 |
| KCS30NH973 | Slippery shoe kit, 30' for 973, 73C flex head. | 025366 | \$673.75 |

Repair Parts for Ford New Holland 972-973 Flex Heads

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|-------|---------|
| CSXNH24 | Repair part, 972 center section, 29" x 24". | 67855 | \$83.94 |
| CSXNH25 | Repair part, 972 left section, 27" x 24". | 68355 | \$76.94 |
| CSXNH26 | Repair part, 972 right section, 27" x 24". | 68357 | \$76.94 |
| CSXNH30 | Repair part for 973, 23" x 24". (Old no. 27) | 69844 | \$69.94 |
| CSXNH31 | Repair part for 973, 29" x 24". (Old no. 28) | 68359 | \$76.94 |
| CSXNH29 | Repair part for 973, 35" x 24". | 68351 | \$76.94 |
| CSXNH22 | Repair part for 972 or 973, gear box cover, 13 1/2" x 7". | 55115 | \$16.50 |
| CSXNH34 | Repair part for 973, divider cover, long section, 7" x 29-11/16". | 08614 | \$24.00 |
| CSXNH35 | Repair part for 973, divider cover, short section, 5" x 13". | 8899 | \$14.12 |

Case New Holland 2020 / New Holland 973, 73C

Made from 1/4" thick, white virgin UHMW, prebent and predrilled. Hammer rivets included with kits. Case 2020 is prior to s/n CBJ020000.

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|------------|-----------------------------------|--------|----------|
| KCS16NH973 | Slippery shoe kit, 16' flex head. | 029933 | \$423.75 |
| KCS18NH973 | Slippery shoe kit, 18' flex head. | 021744 | \$498.75 |
| KCS20NH973 | Slippery shoe kit, 20' flex head. | 008256 | \$561.25 |
| KCS22NH973 | Slippery shoe kit, 22' flex head. | 021558 | \$586.25 |
| KCS24973 | Slippery shoe kit, 24' flex head. | 065858 | \$622.50 |
| KCS25NH973 | Slippery shoe kit, 25' flex head. | 027855 | \$623.75 |
| KCS30NH973 | Slippery shoe kit, 30' flex head. | 025366 | \$673.75 |

Case-IH 1020 Poly Skid Plate Covers Kits

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|------------|--|--------|----------|
| KCS15IHNA | Slippery shoe kit for Case-IH 1020, 15', 32 pcs. | 008236 | \$410.00 |
| KCS175IHNA | Slippery shoe kit for Case-IH 1020, 17.5', 37 pcs. | 021535 | \$439.00 |
| KCS20IHNA | Slippery shoe kit for Case-IH 1020, 20', 42 pcs. | 027838 | \$484.00 |
| KCS225IHNA | Slippery shoe kit for Case-IH 1020, 22.5', 47 pcs. | 042245 | \$528.00 |
| KCS25IHNA | Slippery shoe kit for Case-IH 1020, 25', 53 pcs. | 021744 | \$589.00 |
| KCS30IHNA | Slippery shoe kit for Case-IH 1020, 30', 63 pcs. | 008255 | \$660.00 |



CSXIH17A




CSXIH26

New design, 3/8" thick, has raised alignment blocks for immediate proper placement on the metal pads. Made of an extreme high density UHMW for longer wear. Saves time and money!

Repair Parts for Case-IH 1020

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|-------|---------|
| CSXIH17A | Repair part for Case-IH 1020, main skid plate. 5-3/4" x 7". Replaces CIH number IH #892815. | 8788 | \$12.54 |
| CSXIH1820 | Repair part for Case-IH 1020, 18" x 20", stabilizer. #892817. | 75051 | \$72.24 |
| CSXIH20 | Repair part for Case-IH 1020, 6" x 20", optional bean row. | 27619 | \$23.88 |
| CSXIH26 | Case-IH 1020, 7 7/8" x 8 1/2" (replaces #22 & #21). | 16215 | \$18.02 |
| CSXIH23 | Case-IH 1020, Old style rear gear box cover. 9 1/2" x 5 1/2". | 62011 | \$14.66 |
| CSXIH24 | Case-IH 1020, Old style front gear box cover. 9" x 4". | 62011 | \$14.66 |
| CSXIH27 | Repair part for Case-IH 1020, Gear box cover, newer style, 8" x 8-1/2". | 74114 | \$16.39 |
| CSXIH29 | Repair part for Case-IH 1020, LH end shoe. IH #892818, 1-5/8" x 8-1/2". | 4578 | \$10.78 |
| CSXIH30 | Repair part for Case-IH 1020, RH end shoe, Pre - 1995, 3" x 9-1/8". | 0387 | \$11.86 |
| CSXIH31 | Repair part for Case-IH 1020, RH end shoe, 1995 & later, 3-7/8" x 9". | 93115 | \$16.27 |
| KBHAMA | Pkg of 50 hammer rivets for use in non countersunk holes. | 8498 | \$13.54 |
| KBHAMAS | Pkg of 50 hammer rivets for use in countersunk holes. | 8497 | \$13.54 |



CSXIH1820



CSXIH20



CSXIH23



CSXIH24

Case-IH 820 Poly Skid Plate Covers Kits

Produced from 1/4" thick virgin white UHMW poly, pre-bent and formed to match 1987 and newer skid plate "bend" design. All holes are predrilled. Installs with hammer rivets.

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|--|--------|----------|
| KCS13IH | Slippery shoe kit for IH 820, 13' flex head. | 080035 | \$376.00 |
| KCS15IH | Slippery shoe kit for IH 820, 15' flex head. | 000435 | \$425.00 |
| KCS165IH | Slippery shoe kit for IH 820, 16.5' flex head. | 021538 | \$439.00 |
| KCS175IH | Slippery shoe kit for IH 820, 17.5' flex head. | 027638 | \$459.00 |
| KCS20IH | Slippery shoe kit for IH 820, 20' flex head. | 021938 | \$489.00 |
| KCS225IH | Slippery shoe kit for IH 820, 22.5' flex head. | 029344 | \$549.00 |

Repair Parts for Case-IH 820

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|---|-------|----------|
| CSXIH8 | Repair part for IH 820, 32" x 17 3/4". | 79844 | \$69.96 |
| CSXIH9 | Repair part for IH 820, 6" x 15". | 4965 | \$9.92 |
| CSXIH10 | Repair part for IH 820, 12" x 17 3/4". | 76615 | \$23.82 |
| CSXIH11 | Repair part for IH 820, 21" x 17 3/4". | 57633 | \$52.50 |
| CSXIH12 | Repair part for IH 820, 50" x 17 3/4". | 71574 | \$107.39 |
| CSXIH13 | Repair part for IH 820, 56" x 17 3/4". | 72488 | \$120.38 |
| CSXIH15 | Repair part for IH 820, 42" x 17 3/4". | 57466 | \$92.50 |
| CSXIH16 | Repair part for IH 820, 37" x 17 3/4". | 85556 | \$79.40 |
| CSXIH18 | Repair part for IH 820, 29 1/2" x 17 3/4". | 64444 | \$63.52 |
| KBHAMA | Pkg of 50 hammer rivets for use in non countersunk holes. | 8498 | \$13.54 |
| KBHAMAS | Pkg of 50 hammer rivets for use in countersunk holes. | 8497 | \$13.54 |

MF Rotary Flex and White 900 Poly Skid Kits

Produced from 1/4" thick virgin white UHMW poly, pre-bent to match steel skid plate - undrilled.

All kits include rivets and drill bit. *We do not make the end shoes for these kits.*

| ORDER NO. | DESCRIPTION | STOCK | RETAIL |
|-----------|-------------------------|--------|----------|
| KCS18MF | Slippery shoe kit, 18'. | 008835 | \$485.00 |
| KCS20MF | Slippery shoe kit, 20'. | 002934 | \$490.00 |
| KCS22MF | Slippery shoe kit, 22'. | 084045 | \$506.00 |
| KCS25MF | Slippery shoe kit, 25'. | 029147 | \$524.00 |
| KCS30MF | Slippery shoe kit, 30'. | 025345 | \$544.00 |

